Washing instructions for high-visibility garments

Dirty garments provide poorer protection. High-visibility garments should be washed separately or together with other garments that are approved according to EN ISO 20471. Wash them inside out. Follow the washing instructions on the garment. Do not use detergents containing optical whiteners. Do not use fabric softeners or bleaching agents. Close all zippers before washing. GORE-TEX garments should be tumble dried or ironed at low temperature. The heat helps to reactivate the membrane.

Fristads quality – even after several washes

As a given Fristads quality statement many of our products are approved for industrial laundry. If you see a PRO label in connection to or on a garment from Fristads, you know that it is tested for industrial laundry according to ISO 15797. The PRO label means that the garment can be washed at a minimum of 60˚C. In addition our garments are tested in some of Europe's largest laundries in cooperation with our customers.

Washing instructions

Please note that it is important to use only laundry detergent for colours when washing coloured garments.

Washing, normal process, with specified temperature.

Washing, mild process, with specified temperature.

Washing, very mild process, with specified temperature.

Do not bleach.

Any bleach allowed.

Tumble drying at max. 80º C, normal temperature.

Tumble drying at max 60º C, low temperature.

Do not tumble dry.

Iron at maximum sole-plate temperature of 210°C.

Iron at maximum sole-plate temperature of 160°C.

Iron at maximum sole-plate temperature of 120º C without steam.

Do not iron.

Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F, normal process.

Do not dry clean.