



Washing instructions

Please note it is important to use only laundry detergent for colours when washing coloured garments.

	Washing, normal process, with specified temperature.		Tumble drying at max. 80° C, normal temperature.		Iron at maximum sole-plate temperature of 110° C without steam.
	Washing, mild process, with specified temperature.		Tumble drying at max 60° C, low temperature.		Do not iron.
	Washing, very mild process, with specified temperature.		Do not tumble dry.		Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F, normal process.
	Do not bleach.		Iron at maximum sole-plate temperature of 200°C.		Do not dry clean.
	Any bleach allowed.		Iron at maximum sole-plate temperature of 150°C.		

Washing instructions for high visibility garments

Dirty garments provide poorer protection. High visibility garments should be washed separately or together with other garments that are approved according to EN 471/EN ISO 20471. Wash them inside out. Follow the washing instructions on the garment.

Do not use detergents containing optical whiteners. Do not use fabric softeners or bleaching agents. Close all zips before washing. GORE-TEX® garments should be tumble dried or ironed at low temperature. The heat helps to reactivate the impregnation.

Fristads quality – even after several washes

PRO

As a given Fristads quality statement the industrial workwear range is PRO-labeled. PRO-labelling states that the product is proofed for industrial laundry according to ISO 15797. In addition our garments are also tested in some of Europe's largest laundries in co-operation with our customers.

ISO 15797 is not a standard to which a garment can be certified. It's an industrial test method of industrial laundry where the PRO labelling states the laundry procedure. Look out for the PRO sign next to the article to see if the garment is PRO labeled.